


## FIG. 428KT, 429KTU, 430KTSF

## PIPE SUPPORT KIT INSTALLATION GUIDE

LOCAL: 860 647 1431 • TOLL FREE: 800 243 4844 • ORDERS@EMPIREINDUSTRIES.COM • QUOTES@EMPIREINDUSTRIES.COM




STEP BY STEP INSTALLATION	
1	Measure the distance from the floor to the bottom of the supported pipe or flange.
2	Cut 2" Sched 40 pipe * (3" Sched 40 for sizes 14" and 16") to 6" less than the measurement found in step 1.
3	Thread the saddle assembly onto the 1-1/4" threaded nipple.
4	Place the 2" (3" for sizes 14" and 16") extension pipe * into the base stand coupling.
5	Secure the saddle assembly and reducing coupling with nipple onto the extension pipe. Turn the reducing coupling counter-clockwise until the pipe mates tightly into the saddle.
6	Verify that the complete support assembly is situated directly beneath the supported piping.
7	Welding the extension pipe to both the reducing and base stand coupling is optional.
8	Secure set-screws on both couplings by turning hand-tight plus ¼ turn with crescent wrench or ratchet.
9	Secure base stand with ½" wedge anchors * . Use 7/8" wedge anchors * for sizes 14" and 16".
10	Place U-Bolt over pipe and secure into saddle assembly. (429KT only.)
*	Not supplied



## FIG. 431KTSF

## ADJUSTABLE BOLT ON FLANGE SUPPORT KIT INSTALLATION GUIDE

LOCAL: 860 647 1431 • TOLL FREE: 800 243 4844 • ORDERS@EMPIREINDUSTRIES.COM • QUOTES@EMPIREINDUSTRIES.COM



STEP BY STEP INSTALLATION	
1	Measure the distance from the floor to the bolts on the flange to be supported.
2	Cut 2" Sched 40 pipe * to 6" less than the measurement found in step 1. This will be the extension pipe.
3	Thread the flange bracket assembly onto the 1-1/4" threaded nipple.
4	Place the 2" extension pipe * into the base stand coupling.
5	Secure the flange bracket assembly and reducing coupling with nipple onto the extension pipe. Turn the reducing coupling counter-clockwise until the bracket bolt holes align with the flange bolt holes.
6	Verify that the complete support assembly is situated directly beneath the supported flange.
7	Welding the extension pipe to both the reducing and base stand coupling is optional but not necessary.
8	Secure set-screws on both couplings by turning hand-tight plus ¼ turn with pliers.
9	Secure base stand with ½" wedge anchors * .
10	Insert and tighten flange bolts * to specified torque.
*	Not supplied.